ESCape32 Motor Cutout Mystery

In testing a Sequre 2670 ESCape32 ESC, it worked great with two motors, but with a Dualsky ECO 2826C 850 kv motor, the motor would cut out at high revs. See our YouTube video:

Below are the settings that we had in place. We are looking for an explanation, so please add your insights as comments either at RCJim.com or https://youtu.be/RCScKP3e6YI.

