


ELRS Receiver Test

Transmission Quality with Radiomaster TX16s external ELRS module, 100 mW



© James Massey 2025
permission granted for
non-profit use

From the video it appears that control was maintained throughout the test. When Transmission Quality dropped to zero, it was only momentary.

Delayed control responses
No control response

Walking away from plane with Radiomaster TX16s to "school," then walking back - lots of trees in signal path. 100 MHz full packet rate.